Software:

- DAQ has root6 installed, decoder produces root files compatible with root6
- Analysis macros need to be updated from root5, 8 macros, 0.5 done
- Checkout controls (viewers*, target ladder, Coda)

Hardware:

- Re-install the preamps
- Re-cable ALL* detectors
- We would like to commission the front detectors (not used previously)

Documentation:

- Joe's Wien filter fix (405116 →4054007 →4054075)
    - Cause, impacts, solution, requirements now ect.
- Could really use single document detail all controls, similar to COMTRA, currently set-up but nothing added

Jefferson Lab