ID	Region	Last updated Sep 10, 2020 Task	Start	End	SEP 1 2 3 4	OCT 1 2 3 4	NOV 1 2 3 4	DEC 1 2 3 4	JAN 1 2 3 4	FEB 1 2 3 4	MAR 1 2 3 4	APR 1 2 3 4	MAY 1 2 3 4	JUN 1 2 3 4
1	123	INJ SEG PSS availabe	1-Sep	15-Oct										
2	1	Gun - HV condition tee, test Wien to 15 kV												
3	1	Gun - Vent Gun, swap cathodes, bake, HV condition												
4	1	Gun - Install tee+shed, bake, HV condition												
5	12	Vac - Early opportunity to vent 1I (Y or Wien) for parts												
6	123	Vac - 2I, 1I, 0I laser box disconnects												
7	123	Vac - Vent/remove 2I, 1I, 0I beam line												
8	1	Vac - Complete rebuild of Y												
9	1	Vac - Install/align beamline Gun, 2I, Y												
10	1	Region 1 (Gun, 2I) bake												
11	1	Region 1 reconnects												
12	2	Prebuncher - fab												
13	2	Prebuncher - testing												
14	2	Prebuncher - on girder												
15	2	FG solenoids on girder												
16	2	Wiens - Modify/clean Wien vacuum chamber												
17	2	Wiens - Assemble/map Wien magnet												
18	2	Wiens - Finalize electrodes												
19	2	Wiens - Complete S&A assembly												
20	2	Wiens - On girder												
21	2	Test Wien filter HV												
22	2	Wien cross - build new viewers												
23	2	Wien cross - quads arrive, QA												
24	2	Wien cross - add quads, weld flanges												
25	2	Wien cross - map quads												
26	2	Wien cross - final assembly												
27	2	Region 2 girder install/align												
28	2	Region 2 girder bake												
29	2	Region 2 reconnects												
30	3	A1/A2 - welded cubes ready/clean												
31	3	A1/A2 - MHD coils arrives												
32	3	A1/A2 - MHD assembly/mapping												
33	3	A1/A2 - vacuum aperture assembly & alignment												
34	3	A1/A2 - on girder												
35	3	A1/A2 - remaining girder assembly												
36	3	Region 3 girder - install to tunnel												
37	3	Region 3 girder - bake												
38	3	Region 3 reconnects												
39	123	Phase 1 HCO												
40	123	Commission Week #1 - Gun												
41	123	Commission Week #2 - Setup to chopper												
42	123	Commission Week #3 - Setup to chopper												
43	123	Commission Week #4 - Setup to FC2												
44	123	Commission Week #5 - Wien/Spin												
45	123	CEBAF HCO												
46	123	CEBAF Restore												
47	123	CEBAF Restore												