

From: David Fazenbaker <fazenbak@jlab.org>

Sent: Monday, April 8, 2024 1:46 PM

To: Ruth Deibler <deibler@jlab.org>

Cc: Christian Whalen <ctwhalen@jlab.org>; Walt Akers <akers@jlab.org>; Steven Lassiter <lassiter@jlab.org>

Subject: NPS Meeting

Ruth

Here is my notes. Please add/adjust as you see fit and send out to the group again:

Sweeper magnet in Test Lab

Floor reinforcement in Test Lab (maybe on top)

Lead bricks to lead storage

Lead shield assembly - outside

Detector - no freezing... maybe ESB? Or maybe Fabric Storage? Probably ESB

Detector shield assembly - fabric storage

Cable cart - fabric storage

Cables - 2nd floor of PSB

Rail sections - fabric storage

Platform - fabric storage

Platform support - fabric storage

Platform staircase - fabric storage

Beamline - outside?

Beamline lower support - fabric storage

Downstream corrector magnet - ESB

Other hardware - PSB or ESB

5/19 to 7/17 but likely not till after open house