


# Calorimeter Pedestals

Mike Nycz


- Turned on HV for
  - prl1 & prl2 (LHRS)
  - PreShower & Shower (RHRS)
- Identify any obvious issues
- Identify which channels which delay cables can be switched with S2m
  - S2m is only going to fADC
    - unused delay cables



# LHRS Pedestal Positions

prl1 pedestal positions




prl2 pedestal positions






Channel 31 has an rms nearly double 29

PionRejecotr2 ADCs 10




PionRejecotr2 ADCs 13




# LHRS Change in Pedestal Positions

Change in prL1 Pedestal since March 2017




Change in prL2 Pedestal since March 2017




# RHRS Pedestal Positions

Preshower pedestal positions




Shower pedestal positions




# RHRS Change in Pedestal Positions

Change in PreShower Pedestal since March 2017



Change in Shower Pedestal since March 2017





Thanks

PionRejector1 ADCs 31

