



- STUFF TO DO:
1. MACHINE TAPER ON RECEPTACLE.
 2. ORDER 3 MOD FLANGE TYPES.
 3. ORDER HEAVY WALL TUBE.
 4. ORDER 1/2" DIA. BALL BEARING.
 5. MAKE SFD SHOULDER.
 6. RECEPTACLE TO CERAMIC HV CONNECTOR.
 7. DISKETTS, CHINGS AND FASTENERS.
 8. ELECTRODE.

17.864

THESE
/ BOTH C