


STAC5 to Motor Encoder

STAC5 Encoder Pinout

- 1= A+
- 2= A-
- 3= B+
- 4= B-
- 5= Z+
- 6= Z-
- 7= +5VDC
- 8= GND
- 9-15= NC

15 Pin Female D



Motor Encoder Pinout

- 1= +5VDC
- 2= NC
- 3= A+
- 4= B+
- 5= I+
- 6= GND
- 7= A-
- 8= B-
- 9= I-

9 Pin Male D

